



## State of Utah

### Department of Natural Resources

ROBERT L. MORGAN  
*Executive Director*

### Division of Oil, Gas & Mining


LOWELL P. BRAXTON  
*Division Director*

OLENE S. WALKER  
*Governor*

GAYLE F. McKEACHNIE  
*Lieutenant Governor*

June 4, 2004

TO: Minerals File

FROM: Doug Jensen, Senior Reclamation Engineer 

SUBJECT: Site Inspection, Staker Parson Companies, Lehi Quarry,  
M/049/031, Utah County, Utah

Date of Inspection: May 27, 2004  
Time of Inspection: 11:00 a.m.  
Conditions: Partly Sunny  
Participants: Mike Dalley, Staker Parson, Doug Jensen, Lynn Kunzler,  
DOGM

#### **Purpose of Inspection:**

Review site conditions for bond escalation purposes.

#### **Getting to the site:**

The site is located two miles west of the intersection of SR-73 and Redwood Road.

#### **Observations:**

There was no mining taking place at the time of our visit. The only people on the site was a crew working on the crusher. The crew was in the process of installing a control room for the crusher.

There is an asphalt plant (picture included in this report) located on-site which Mike indicated is for sale. This plant is to be sold and removed from the site.

We toured the quarry site to review an area that was shown on their latest map as disturbed. This area was apparently disturbed in the early stages of the operation to provide material for a berm. The area has been revegetated and will not be considered a part of the permit area for bonding purposes. The berm created at the time is just above a laydown area (picture included), which was used by Western Aggregate (former operators) to store old and used equipment.

Page 2

Staker Parson Lehi Quarry

M/049/031

Inspection Date: May 27, 2004; Report Date: June 4, 2004

The next area visited was an area above the quarry (picture included) where material, which appears to be from a wash plant, has been stored. There were two small dumps in this area which encompasses approximately 3 acres.

A photo showing the entire site was taken from a hill above the quarry.

There were no areas of concern at the site. All disturbances at the site are within the permitted and bonded area. With this tour completed, escalation of the bond can now move forward.

**Conclusions and Recommendations:**


There were no areas of concern at the mine. The quarry was permitted for a fifty-year life; therefore, mining can continue to the north for quite some time before the extent of the permit is disturbed.

DJ:jb

cc: Mike Dalley, Staker & Parson Companies

O:\M049-Utah\m0490031-lehi\inspections\ins-05272004.doc





ASPHALT PLANT






LAYDOWN AREA





PLANT OVERVIEW



5/27/2000

WASH MATERIAL DUMPS